

the arm of a setter which was a fixture. His head, I think, struck a portion of the arm and seat so that it might have given 2 bumps. I never knew the superintendent to fail to inquire into cases of that sort. I don't remember a case that came under my observation that I did not inquire into, except perhaps such a case as I could see evidence that it was being treated by the physician.

The kitchen matters have been very much improved since I have known that place. As I first saw it it was under the centre building, provided with a tolerable system of apparatus. It was obnoxious to the centre building and all the wards by reason of the odors passing up into them, and it could not be prevented. The system of heating and ventilation so far as there was one in regard to ventilation, was such that the odors must pass up into all the wards or pass over them. The steam and moisture were injuring the floor timbers throughout the centre building to a degree